

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |      |       |                   |
|-----------------|----------------------------------------|------|------|-------|-------------------|
| INSPECTION DATE | 2026/8/20                              | MAKE | CAT  | MODEL | 312FGC            |
| SERIAL          | CAT0312FKFKE00249                      |      |      | STAMP | CAT0312FKFKE00249 |
| HR METER        | E3894 / E3903                          | HR   | YEAR | YR    |                   |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |      | SHOE  | 500G PADS         |

|                           |       |       |                                      |          |
|---------------------------|-------|-------|--------------------------------------|----------|
| ENGINE : MODEL            |       | C3.4B | S/N                                  | CNW03702 |
| Oil leakage               | FAIR  | Attn  |                                      |          |
| Blow-By                   | FAIR  | Attn  | A LITTLE · MIDDLE · SEVERE           |          |
| Sound                     | FAIR  | Attn  |                                      |          |
| Oil                       | FAIR  | Attn  |                                      |          |
| Exhaust Color             | FAIR  | Attn  |                                      |          |
| US EPA                    | YES   | NO    |                                      |          |
| MAIN PUMP                 |       |       |                                      |          |
| Sound                     | FAIR  | Attn  |                                      |          |
| Oil leakage               | FAIR  | Attn  |                                      |          |
| Power                     | FAIR  | Attn  |                                      |          |
| COOLING SYSTEM            |       |       |                                      |          |
| Radiator                  | FAIR  | Attn  |                                      |          |
| Oil Cooler                | FAIR  | Attn  |                                      |          |
| OPERATING SYSTEM          |       |       |                                      |          |
| Swing                     | FAIR  | Attn  |                                      |          |
| Travel                    | FAIR  | Attn  | HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION |          |
| INTERIOR See Photos. 写真参照 |       |       |                                      |          |
| INTERIOR COND.            | CLEAN | FAIR  | DIRTY                                |          |
| Operator's Seat           | FAIR  | Attn  | 破れあり MUCH WORN                       |          |
| Glasses                   | FAIR  | Attn  |                                      |          |
| AirCon                    | A/C   | H/C   | H only                               | C only   |
| None                      |       |       |                                      |          |
| BOOM / ARM / BKT          |       |       |                                      |          |
| Boom                      | FAIR  | Attn  |                                      |          |
| Boom Cylinder             | FAIR  | Attn  | 左油漏れ小 LEFT CYLINDER: OIL LEAKING     |          |
| Arm                       | FAIR  | Attn  |                                      |          |
| Arm Cylinder              | FAIR  | Attn  |                                      |          |
| ATTACHMENT                | FAIR  | Attn  |                                      |          |
| BKT Cylinder              | FAIR  | Attn  |                                      |          |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。