

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/8/26	MAKE	TADANO	MODEL	AT-146-3
SERIAL No.	PLATE : 228876			STAMP : 228876	
HR METER	2293	HR	Odometer	32289	km
YEAR	YR				
CHASSIS	MODEL NKR85Y			No. 7004836	
SHOE				TIRE SIZE	215/70R17.5
MAX HIGHT	15.1			m	
MAX WEIGHT				250	kg

ENGINE : MODEL 4JJ1 S/N 1M6044	
Oil leakage	☒ FAIR • Attn
Blow-By	☒ FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR • Attn
Oil	☒ FAIR • Attn
Exhaust Color	☒ FAIR • Attn
US EPA	YES ☒ NO
OPERATION PUMP	
Sound	☒ FAIR • Attn
Oil leakage	☒ FAIR • Attn
Power	☒ FAIR • Attn
COOLING SYSTEM	
Radiator	☒ FAIR • Attn
Oil Cooler	☒ FAIR • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	AT ☒ MT
No. OF GEARS	6 GEARS
Transmission	☒ FAIR • Attn
4WD	4WD ☒ 2WD
Travel	☒ FAIR • Attn
Swing	☒ FAIR • Attn
FOOT BRAKE	☒ FAIR • Attn
PARKING BRAKE	☒ FAIR • Attn
BOOM	
No. of Section	3 SECTIONS
DERRICKING CYL.	☒ FAIR • Attn
EXTENSION CYL.	☒ FAIR • Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	☒ CLEAN • FAIR • DIRTY
Operator's Seat	☒ FAIR • Attn
Glasses	☒ FAIR • Attn
AirCon	☒ A/C • H/C • H only • C only • None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR • WORN • UNEVEN WEAR
COMMENT	
OUTRIGGERS X • ☒ H	
OUTRIGGERS COND.	☒ FAIR • Attn
COMMENT	
最高出力 MAXIMUM OUTPUT: 110kW/2800rpm	
スペアタイヤあり W/SPARE TIRES	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。