

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/9/7	MAKE	CAT	MODEL	910-14A
SERIAL	CAT00910CJW201868			STAMP	CAT00910CJW201868
HR METER	6838	HR	Odometer	12662	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE			TIRE SIZE	13.00-24

ENGINE : MODEL C3.6 S/N	
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn
US EPA	<u>YES</u> · NO
OPERATION PUMP	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	<u>PS</u> · DD
Transmission	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
FOOT BRAKE	<u>FAIR</u> · Attn
PARKING BRAKE	<u>FAIR</u> · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY
Operator's Seat	<u>FAIR</u> · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · <u>None</u>
FRONT & CYLINDERS	
Arm	<u>FAIR</u> · Attn セミロング SEMI-LONG
Bell crank	<u>FAIR</u> · Attn
Bucket	<u>FAIR</u> · Attn
Articulate	<u>FAIR</u> · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	<u>FAIR</u> · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE <u>WHEEL STEERING</u> / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · <u>NO</u>
ATTACHMENTS	
STD BKT	<u>YES</u> · OTHER
BLADE	YES · <u>NO</u> Piping for Tilt YES · <u>NO</u>
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。