

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/24	MAKE	KOBELCO	MODEL	SK135SR-3F
SERIAL	YY07-27665		STAMP	YY07-27665	
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4
COMMENT					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER())				
Lever	LONG	▪	(WRIST)		
Multi	(MULTI)	▪	2	▪	NO
ARM-CRANE	YES	▪	(NO)		
BLADE	(YES)	▪	NO		
OFFSET	YES	▪	(NO)		
OFFSET Cylinder	FAIR	▪	Attn		
Piping	(YES)	▪	NO	Breaker only	▪ Multi 5
COMMENT					
E/Gフード欠 ENGINE HOOD: MISSING					
ボディリペイントあり BODY: REPAINTED					
バックモニター不良 BACK MONITOR: MALFUNCTION					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。