INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/28	MAKE	KOMATSU	MODEL	PC450-6
SERIAL	10354			STAMP	PC450-10354
HR METER	12614 HR			YEAR	YR
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL S/N		
Oil leakage	FAIR ・(Attn)	油漏れあり OIL LEAKING
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	FAIR ・(Attn)	オイル混入あり OIL: MIXED
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	ガタあり SWING: LOOSE
Travel	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・ FAIR・ (DIRTY)	
Operator's Seat	(FAIR)・ Attn	
Glasses	(FAIR)・ Attn	
AirCon	(A/C)・ H/C・ H only・ C only・ None	
BOOM / ARM / BKT		
Boom	FAIR ・(Attn)	*1
Boom Cylinder	(FAIR)・ Attn	
Arm	(FAIR)・ Attn	ガタあり LOOSE
Arm Cylinder	(FAIR)・ Attn	
ATTACHMENT	(FAIR)・ Attn	ガタあり LOOSE
BKT Cylinder	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG・(WRIST)	
Multi	MULTI・2・(NO)	
ARM-CRANE	YES・(NO)	
BLADE	YES・(NO)	
OFFSET	YES・(NO)	
OFFSET Cylinder	FAIR・Attn	
Piping	YES・(NO)	Breaker only・Multi
COMMENT		
底板欠 SOME UNDER COVER: MISSING		
全体的にホースひび割れ、破れ多い SOME HOSES: DAMAGED		
コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING		
A/C冷えない A/C: MALFUNCTION		
*1 自然降下あり(ブームで車体上げたまま保持不可)		
*1 HYDRAULIC DRIFT		
(UNABLE TO KEEP THE BODY AT THE PUSH-UP POSITION BY BOOM)		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。