

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/21	MAKE	KOBELCO	MODEL	SK200-8
SERIAL	YN12-62825		STAMP	YN12-62825	
HR METER	9251	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		J05E	S/N
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn	破れあり TORN	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn		
Arm	FAIR · Attn		
Arm Cylinder	FAIR · Attn		
ATTACHMENT	FAIR · Attn	ガタあり LOOSE	
BKT Cylinder	FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照		3
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		
COMMENT		
BKT STD / SLOPE / NARROW / SKELETON / OTHER ()		
Lever	LONG ▪ WRIST	
Multi	MULTI ▪ 2 ▪ NO	
ARM-CRANE	YES ▪ NO	*1
BLADE	YES ▪ NO	
OFFSET	YES ▪ NO	
OFFSET Cylinder	FAIR ▪ Attn	
Piping	YES ▪ NO	Breaker only ▪ Multi
COMMENT		
底板欠 SOME UNDER COVERS: MISSING		
リペイントあり REPAINTED		
*1 C033エラー、100%荷重消えない、ブザー音あり		
*1 "C033" ERROR & "100% LOAD" DISPLAY: NOT DISAPPEARING,		
WARNING SOUNDS: ON		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		
		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。