

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |            |
|-----------------|----------------------------------------|------|---------|-------------------|------------|
| INSPECTION DATE | 2026/8/24                              | MAKE | KOMATSU | MODEL             | PC78US-6N0 |
| SERIAL          | 11651                                  |      | STAMP   | KMTPC030E01011651 |            |
| HR METER        | 5464                                   | HR   | YEAR    | YR                |            |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 450G PADS         |            |

|                           |       |       |                            |        |        |
|---------------------------|-------|-------|----------------------------|--------|--------|
| ENGINE :                  |       | MODEL | 4D95LE-3                   | S/N    | 123431 |
| Oil leakage               | FAIR  | Attn  |                            |        |        |
| Blow-By                   | FAIR  | Attn  | A LITTLE · MIDDLE · SEVERE |        |        |
| Sound                     | FAIR  | Attn  |                            |        |        |
| Oil                       | FAIR  | Attn  |                            |        |        |
| Exhaust Color             | FAIR  | Attn  |                            |        |        |
| US EPA                    | YES   | NO    |                            |        |        |
| MAIN PUMP                 |       |       |                            |        |        |
| Sound                     | FAIR  | Attn  |                            |        |        |
| Oil leakage               | FAIR  | Attn  |                            |        |        |
| Power                     | FAIR  | Attn  |                            |        |        |
| COOLING SYSTEM            |       |       |                            |        |        |
| Radiator                  | FAIR  | Attn  |                            |        |        |
| Oil Cooler                | FAIR  | Attn  |                            |        |        |
| OPERATING SYSTEM          |       |       |                            |        |        |
| Swing                     | FAIR  | Attn  | ガタあり SWING: LOOSE          |        |        |
| Travel                    | FAIR  | Attn  |                            |        |        |
| INTERIOR See Photos. 写真参照 |       |       |                            |        |        |
| INTERIOR COND.            | CLEAN | FAIR  | DIRTY                      |        |        |
| Operator's Seat           | FAIR  | Attn  |                            |        |        |
| Glasses                   | FAIR  | Attn  |                            |        |        |
| AirCon                    | A/C   | H/C   | H only                     | C only | None   |
| BOOM / ARM / BKT          |       |       |                            |        |        |
| Boom                      | FAIR  | Attn  |                            |        |        |
| Boom Cylinder             | FAIR  | Attn  |                            |        |        |
| Arm                       | FAIR  | Attn  |                            |        |        |
| Arm Cylinder              | FAIR  | Attn  |                            |        |        |
| ATTACHMENT                | FAIR  | Attn  |                            |        |        |
| BKT Cylinder              | FAIR  | Attn  |                            |        |        |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。