

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |       |            |
|-----------------|----------------------------------------|------|---------|-------|------------|
| INSPECTION DATE | 2026/9/3                               | MAKE | KOBELCO | MODEL | SK75SR-3   |
| SERIAL          | YT07-25224                             |      |         | STAMP | YT07-25224 |
| HR METER        | 7825                                   | HR   | YEAR    | YR    |            |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |         | SHOE  | 450G PADS  |

ENGINE : MODEL 4LE2 S/N 287620

|               |      |      |                            |
|---------------|------|------|----------------------------|
| Oil leakage   | FAIR | Attn |                            |
| Blow-By       | FAIR | Attn | A LITTLE · MIDDLE · SEVERE |
| Sound         | FAIR | Attn |                            |
| Oil           | FAIR | Attn |                            |
| Exhaust Color | FAIR | Attn |                            |
| US EPA        | YES  | NO   |                            |

MAIN PUMP

|             |      |      |  |
|-------------|------|------|--|
| Sound       | FAIR | Attn |  |
| Oil leakage | FAIR | Attn |  |
| Power       | FAIR | Attn |  |

COOLING SYSTEM

|            |      |      |  |
|------------|------|------|--|
| Radiator   | FAIR | Attn |  |
| Oil Cooler | FAIR | Attn |  |

OPERATING SYSTEM

|        |      |      |  |
|--------|------|------|--|
| Swing  | FAIR | Attn |  |
| Travel | FAIR | Attn |  |

INTERIOR See Photos. 写真参照

|                 |                                        |
|-----------------|----------------------------------------|
| INTERIOR COND.  | CLEAN · FAIR · DIRTY                   |
| Operator's Seat | FAIR · Attn カバー下破れ大 TORN, W/SEAT COVER |
| Glasses         | FAIR · Attn                            |
| AirCon          | A/C · H/C · H only · C only · None     |

BOOM / ARM / BKT

|               |      |      |  |
|---------------|------|------|--|
| Boom          | FAIR | Attn |  |
| Boom Cylinder | FAIR | Attn |  |
| Arm           | FAIR | Attn |  |
| Arm Cylinder  | FAIR | Attn |  |
| ATTACHMENT    | FAIR | Attn |  |
| BKT Cylinder  | FAIR | Attn |  |

UNDERCARRIAGE : See Photos. 写真参照

|                                                              |   |
|--------------------------------------------------------------|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
|--------------------------------------------------------------|---|

COMMENT

.....

.....

.....

.....

BKT (STD / SLOPE / NARROW / SKELETON / OTHER ( ) )

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only Multi

COMMENT

.....

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。