

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/8/27	MAKE	KOMATSU	MODEL	D31S-18
SERIAL	40078			STAMP	D31S16-32429
HR METER	7061	HR	SHOE	400G	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL 6D95L-1 S/N 36084	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS · DD DIFF. STEERING YES · NO
Transmission	FAIR · Attn
Travel	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 破れあり TORN
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
BLADE & CYLINDERS	
BLADE	FAIR · Attn
CYLD.(R)	FAIR · Attn にじみあり OIL Oozing
CYLD.(L)	FAIR · Attn
TILT CYLD	FAIR · Attn
ANGLE CYLD	FAIR · Attn

UNDERCARRIAGE See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
左右操向ケース内水混入あり WATER: MIXED INTO THE STEERING CLUTCH CASE & STEERING BRAKE CASE	
左キャリアローラー変形あり LEFT CARRIER ROLLER: BENT ピンブッシュ割れあり SOME PIN BUSHES: BROKEN	
Ripper	MULTI · S/S Shanks PCS
Ripper CYLD.	FAIR · Attn
COMMENT	
ドーザーショベル DOZER-SHOVEL ヒーター故障あり HEATER: MALFUNCTION 左バケットシリンダーにじみあり LEFT BUCKET CYLINDER: OIL Oozing プレートとスタンプが違う SERIAL NUMBER: NOT EQUAL AT PLATE & STAMP	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。