

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/24	MAKE	KUBOTA	MODEL	U-30-5
SERIAL	76022		STAMP	76022	
HR METER	6431	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300R	

ENGINE :		MODEL	S/N	7DP5263
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE	MIDDLE SEVERE
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れ大 HUGE CUTS	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE :						See Photos.								写真参照							
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																				4	
COMMENT																					
BKT		(STD / SLOPE / NARROW / SKELETON / OTHER())																			
Lever		LONG ▪ WRIST																			
Multi		MULTI ▪ 2 ▪ NO																			
ARM-CRANE		YES ▪ NO																			
BLADE		YES ▪ NO																			
OFFSET		YES ▪ NO																			
OFFSET Cylinder		FAIR ▪ Attn																			
Piping		YES ▪ NO Breaker only ▪ Multi																			
COMMENT																					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																				4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。