

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/25	MAKE	HITACHI	MODEL	ZX50U-5A
SERIAL	HCMAEBA0C00052163			STAMP	HCMAEBA0C00052163
HR METER	843 + 3010	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE			SHOE	400R

ENGINE : MODEL 4TNV88 **S/N** S9800

Oil leakage	<u>FAIR</u> ・ Attn	
Blow-By	<u>FAIR</u> ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	<u>FAIR</u> ・ Attn	
Oil	<u>FAIR</u> ・ Attn	
Exhaust Color	<u>FAIR</u> ・ Attn	
US EPA	YES ・ <u>NO</u>	

MAIN PUMP

Sound	<u>FAIR</u> ・ Attn	
Oil leakage	<u>FAIR</u> ・ Attn	
Power	<u>FAIR</u> ・ Attn	

COOLING SYSTEM

Radiator	<u>FAIR</u> ・ Attn	
Oil Cooler	<u>FAIR</u> ・ Attn	

OPERATING SYSTEM

Swing	<u>FAIR</u> ・ Attn	
Travel	<u>FAIR</u> ・ Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN ・ <u>FAIR</u> ・ DIRTY
Operator's Seat	<u>FAIR</u> ・ Attn 破れあり CUT
Glasses	FAIR ・ Attn
AirCon	A/C ・ H/C ・ H only ・ C only ・ <u>None</u>

BOOM / ARM / BKT

Boom	<u>FAIR</u> ・ Attn	
Boom Cylinder	<u>FAIR</u> ・ Attn	
Arm	<u>FAIR</u> ・ Attn	
Arm Cylinder	<u>FAIR</u> ・ Attn	
ATTACHMENT	<u>FAIR</u> ・ Attn	ガタあり LOOSE
BKT Cylinder	<u>FAIR</u> ・ Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

COMMENT

右側キャリアローラー欠 RIGHT CARRIER ROLLER: MISSING

BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())

Lever LONG ・ WRIST

Multi MULTI ・ 2 ・ NO

ARM-CRANE YES ・ NO *1

BLADE YES ・ NO

OFFSET YES ・ NO

OFFSET Cylinder FAIR ・ Attn

Piping YES ・ NO Breaker only ・ Multi

COMMENT

*1 入るがW:0051エラー表示あり

*1 "W:0051" ERROR DISPLAY (CRANE MODE: ABLE TO TURN ON)

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。