

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/8/25	MAKE	KOMATSU	MODEL	WA270-6
SERIAL	77257			STAMP	WA103-77257
HR METER	UNKNOWN	HR	Odometer	UNKNOWN	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25

ENGINE : MODEL 6D107E-1 S/N 26597156	
Oil leakage	☒ FAIR • Attn
Blow-By	☒ FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR • Attn
Oil	☒ FAIR • Attn
Exhaust Color	☒ FAIR • Attn
US EPA	YES • ☒ NO
OPERATION PUMP	
Sound	☒ FAIR • Attn
Oil leakage	☒ FAIR • Attn
Power	☒ FAIR • Attn
COOLING SYSTEM	
Radiator	☒ FAIR • Attn
Oil Cooler	☒ FAIR • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ PS • DD
Transmission	☒ FAIR • Attn
Travel	☒ FAIR • Attn
FOOT BRAKE	☒ FAIR • Attn
PARKING BRAKE	☒ FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY
Operator's Seat	☒ FAIR • Attn
Glasses	☒ FAIR • Attn
AirCon	☒ A/C • H/C • H only • C only • None
FRONT & CYLINDERS	
Arm	☒ FAIR • Attn
Bell crank	☒ FAIR • Attn
Bucket	☒ FAIR • Attn
Articulate	FAIR • ☒ *1

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR • WORN • UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	☒ YES • NO *2
ATTACHMENTS	
STD BKT	☒ YES • OTHER
BLADE	YES • ☒ NO Piping for Tilt YES • ☒ NO
COMMENT	
モニター不良 (HR、km不明)	
MONITOR: MALFUNCTION (HR METER & ODOMETER: UNKNOWN)	
リペイントあり REPAINTED	
A/C冷えない A/C: MALFUNCTION	
*1 左シリンダーにじみあり LEFT CYLINDER: OIL Oozing	
*2 S/Wはあるがモニター確認不可	
*2 UNABLE TO CHECK THE RIDE CONTROL MARK AT INDICATOR	
(JUST W/SWITCH)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。