

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/9/16	MAKE	HITACHI	MODEL	LX80-7
SERIAL	S51P000132			STAMP	S51-00132
HR METER	8878	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	18.4-24 10PR

ENGINE : MODEL		4BG1	S/N	164382
Oil leakage	FAIR	Attn	E/G周りにじみあり AROUND ENGINE: OIL OOZING	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE *1	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn	白煙大 MUCH WHITE FUMES	
US EPA	YES	NO		

OPERATION PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn	油漏れあり OIL LEAKING	
Power	FAIR	Attn		

COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		

TRANSMISSION & TRAVEL				
T/M TYPE	PS	DD		
Transmission	FAIR	Attn		
Travel	FAIR	Attn		
FOOT BRAKE	FAIR	Attn		
PARKING BRAKE	FAIR	Attn		

INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only · None

FRONT & CYLINDERS				
Arm	FAIR	Attn	*2	
Bell crank	FAIR	Attn		
Bucket	FAIR	Attn	シリンダー油漏れあり CYLINDER: OIL LEAKING	
Articulate	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR · WORN · UNEVEN WEAR

COMMENT	
タコメーター TACHOMETER: 51289km	
下周り油漏れあり BOTTOM: OIL LEAKING	
タイヤ傷あり TIRES: CUTS	
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / LEVER STEERING
RIDE CONTROL	YES · NO

ATTACHMENTS			
STD BKT	YES · OTHER		
BLADE	YES · NO	Piping for Tilt	YES · NO

COMMENT	
スピードメーター不良 SPEED METER: MALFUNCTION	
*1 E/G内部摩耗によりブローバイガス大、ブローバイホース油漏れあり、 ブローバイホース改造してマフラーへ繋げている	
*1 MUCH BLOW-BY GAS (DUE TO INTERNAL ENGINE WEARING), BLOW-BY HOSE: OIL LEAKING, CONNECTING WITH MUFFLER	
*2 左右シリンダー油漏れあり CYLINDERS: OIL LEAKING	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
--	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。