

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/9/4	MAKE	HITACHI	MODEL	ZW30			
SERIAL	RYU4EK00A00003658			STAMP	S65-03658			
HR METER	1062	HR	Odometer	—	km	YEAR	2015	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	12.5/70-16 6PR			

ENGINE : MODEL		D1803	S/N	7EY5093
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	固着あり STUCK
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY				
Operator's Seat	FAIR ・ Attn	塗料付着あり A LITTLE PAINTY			
Glasses	FAIR ・ Attn				
AirCon	A/C	・	H/C	・	H only ・ C only ・ None

FRONT & CYLINDERS

Arm	FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

TIRE WEAR (FAIR • WORN • UNEVEN WEAR)

COMMENT

STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL	YES	☐	NO	☒
--------------	-----	--------------------------	----	-------------------------------------

ATTACHMENTS

STD BKT	☒ YES • ☐ OTHER
---------	--

BLADE	YES ▪ ☒ NO	Piping for Tilt	YES ▪ ☒ NO
-------	---	-----------------	---

COMMENT

This image shows a blank sheet of white paper with horizontal ruling lines. The lines are evenly spaced and extend across the width of the page. On the left side, there is a vertical margin line, creating a narrow left margin. The paper appears to be from a notebook or a standard ruled document.

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **3**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。