

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/9/4	MAKE	YANMAR	MODEL	V3-7			
SERIAL	70543		STAMP	V37-70543				
HR METER	758	HR	Odometer	—	km	YEAR	2015	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	12.5/70-16 6PR			

ENGINE : MODEL		S/N	04058
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY				
Operator's Seat	FAIR •	Attn			
Glasses	FAIR •	Attn			
AirCon	A/C •	H/C •	H only •	C only •	None

FRONT & CYLINDERS

Arm	FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR (FAIR • WORN • UNEVEN WEAR)	

COMMENT

STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING

RIDE CONTROL	YES	☒ NO
--------------	-----	-------------------------------------

ATTACHMENTS

STD BKT	YES • OTHER		
BLADE	YES • NO	Piping for Tilt	YES • NO

COMMENT

This image shows a blank sheet of white paper with horizontal ruling lines. A solid black vertical line runs down the left side, creating a margin. The rest of the page is filled with evenly spaced horizontal black lines. There are no markings or text on the page.

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。