

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE		2026/9/8		CATEGORY		MULTI PLOW			
MAKE	HITACHI				MODEL	LX-80			
SERIAL	016				STAMP	NOT FOUND			
HR METER	—		HR	Odometer	km		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE			TIRE		

ENGINE	MODEL		S/N		
Oil leakage	FAIR ・ Attn		Oil	FAIR ・ Attn	
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color	FAIR ・ Attn	
Sound	FAIR ・ Attn		EPA	YES ・ NO	

CONDITION	FAIR ・ Attn	
未確認 OPERATION: NOT CHECKED		

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	—	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR
COMMENT			
CENTER: 60 ϕ × 85mm, SIDES: 50 ϕ × 103mm			
左右底面ソリ欠 SLEDS OF BLADE: MISSING			
取付ホース4本あり W/4 HOSES			
ホースにじみあり SOME HOSE: OIL OOZING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。