INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/9/25	MAKE	HITACHI	MODEL	ZX225USR
SERIAL	HCM1GD00L00112137			STAMP	HCM1GD00L00112137
HR METER	13603 HR			YEAR	YR
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE			SHOE	800G

ENGINE : MODEL 6BG1 S/N 186892		
Oil leakage	(FAIR) · Attn	
Blow-By	FAIR · (Attn)	A LITTLE · (MIDDLE) · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	一部読めない STICKER: PARTLY UNREADABLE
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	FAIR · (Attn)	油漏れ小 OIL LEAKING
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	ガタあり SWING: LOOSE
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · (DIRTY)	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	(FAIR) · Attn	ガタあり LOOSE
Boom Cylinder	FAIR · (Attn)	左右油漏れ小 CYLINDERS: OIL LEAKING
Arm	(FAIR) · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · (Attn)	油漏れ小 OIL LEAKING
ATTACHMENT	(FAIR) · Attn	
BKT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG · (WRIST)	
Multi	MULTI · 2 · (NO)	
ARM-CRANE	(YES) · NO	
BLADE	YES · (NO)	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · (NO)	Breaker only · Multi

COMMENT

コントロールバルブ油漏れ小 CONTROL VALVE: OIL LEAKING

ローアイドルで負荷掛けるとエンストする

ENGINE STALLING WITH ENGINE LOAD INCREASING IN LOW IDLING

A/Cベルト欠 A/C: NO BELT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。