

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2026/9/17	MAKE	HITACHI	MODEL	ZX125W
SERIAL	HCM11P00C00006009			STAMP	125W-6009
HR METER	7875	HR	Odometer	26886	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE	9.00-20 12PR		

ENGINE : MODEL 6BG1 S/N		UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage	FAIR • Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE	TIRE WEAR FAIR • WORN • UNEVEN WEAR	
Sound	FAIR • Attn	COMMENT 	
Oil	FAIR • Attn		
Exhaust Color	FAIR • Attn		
US EPA	YES • NO		
MAIN PUMP			
Sound	FAIR • Attn	BKT	STD / SLOPE / NARROW / SKELETON / OTHER()
Oil leakage	FAIR • Attn	Lever	LONG • WRIST
Power	FAIR • Attn	Multi	MULTI • 2 • NO
COOLING SYSTEM		ARM-CRANE	YES • NO
Radiator	FAIR • Attn	BLADE	YES • NO
Oil Cooler	FAIR • Attn	OFFSET	YES • NO
OPERATING SYSTEM		OFFSET Cylinder	FAIR • Attn
Swing	FAIR • Attn ガタあり SWING: LOOSE	Piping	YES • NO Breaker only • Multi
Travel	FAIR • Attn	OUTRIGGERS COND.	FAIR • Attn
INTERIOR See Photos. 写真参照		COMMENT	
INTERIOR COND.	CLEAN • FAIR • DIRTY	A/Cベルト鳴きあり A/C BELT: NOISES	
Operator's Seat	FAIR • Attn 破れあり CUTS	CAB下アンダーカバー欠 UNDER COVERS OF CAB: MISSING	
Glasses	FAIR • Attn	コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING	
AirCon	A/C • H/C • H only • C only • None		
BOOM / ARM / BKT			
Boom	FAIR • Attn		
Boom Cylinder	FAIR • Attn		
Arm	FAIR • Attn ガタあり LOOSE		
Arm Cylinder	FAIR • Attn		
ATTACHMENT	FAIR • Attn		
BKT Cylinder	FAIR • Attn にじみあり OIL OOZING		
		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。