

INSPECTION SHEET 検品書
GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE	2026/9/28	CATEGORY	GENERATOR / COMPRESSOR / WELDER		
MAKE	DENYO		MODEL	DCA-100LSIB	
SERIAL	3924769		STAMP	NOT FOUND	
HR METER	11451	HR	TIRE SIZE	YEAR	YR

ENGINE :	MODEL	ISUZU 4HK1	S/N	760927
Oil leakage	☒ FAIR ▪ Attn		Oil	☒ FAIR ▪ Attn
Blow-By	☒ FAIR ▪ Attn	A LITTLE ▪ MIDDLE ▪ SEVERE	Exhaust Color	☒ FAIR ▪ Attn
Sound	☒ FAIR ▪ Attn		Radiator	☒ FAIR ▪ Attn

GENERATOR				
RATED POWER	80 / 100	KVA	Leaking Breaker Condition	☒ FAIR ▪ Attn
RATED AMPERE	231, 115 / 262, 131	A	Insulation Condition	☒ FAIR ▪ Attn
Output Terminal	☒ FAIR ▪ Attn			

COMPRESSOR				
RATED PRESSURE		Mpa Kgf/cm2	Unload Condition	☐ FAIR ▪ Attn
RATED AIR FLOW		m3/min	Receiver Tank Condition	☐ FAIR ▪ Attn
Compressor Oil Leak	☐ FAIR ▪ Attn		Safety Valve Condition	☐ FAIR ▪ Attn

CONDITION	☒ FAIR ▪ Attn	

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR
--	---	-----------	---------------------------

COMMENTS
--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。