

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |           |
|-----------------|----------------------------------------|------|---------|-------------------|-----------|
| INSPECTION DATE | 2026/9/29                              | MAKE | HITACHI | MODEL             | ZX200LC-3 |
| SERIAL          | HCM1U100A00225060                      |      | STAMP   | HCM1U100A00225060 |           |
| HR METER        | 3962                                   | HR   | YEAR    | YR                |           |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 800G              |           |

|                  |                                      |                            |     |        |
|------------------|--------------------------------------|----------------------------|-----|--------|
| ENGINE : MODEL   |                                      | 4HK1                       | S/N | 708948 |
| Oil leakage      | (FAIR) · Attn                        |                            |     |        |
| Blow-By          | (FAIR) · Attn                        | A LITTLE · MIDDLE · SEVERE |     |        |
| Sound            | (FAIR) · Attn                        |                            |     |        |
| Oil              | (FAIR) · Attn                        |                            |     |        |
| Exhaust Color    | (FAIR) · Attn                        |                            |     |        |
| US EPA           | YES · (NO)                           |                            |     |        |
| MAIN PUMP        |                                      |                            |     |        |
| Sound            | (FAIR) · Attn                        |                            |     |        |
| Oil leakage      | (FAIR) · Attn                        |                            |     |        |
| Power            | (FAIR) · Attn                        |                            |     |        |
| COOLING SYSTEM   |                                      |                            |     |        |
| Radiator         | (FAIR) · Attn                        |                            |     |        |
| Oil Cooler       | (FAIR) · Attn                        |                            |     |        |
| OPERATING SYSTEM |                                      |                            |     |        |
| Swing            | (FAIR) · Attn                        |                            |     |        |
| Travel           | (FAIR) · Attn                        |                            |     |        |
| INTERIOR         |                                      | See Photos. 写真参照           |     |        |
| INTERIOR COND.   | CLEAN · (FAIR) · DIRTY               |                            |     |        |
| Operator's Seat  | (FAIR) · Attn                        | 破れあり TORN                  |     |        |
| Glasses          | (FAIR) · Attn                        |                            |     |        |
| AirCon           | (A/C) · H/C · H only · C only · None |                            |     |        |
| BOOM / ARM / BKT |                                      |                            |     |        |
| Boom             | (FAIR) · Attn                        |                            |     |        |
| Boom Cylinder    | (FAIR) · Attn                        |                            |     |        |
| Arm              | (FAIR) · Attn                        | 補強、ガタあり REINFORCED, LOOSE  |     |        |
| Arm Cylinder     | (FAIR) · Attn                        |                            |     |        |
| ATTACHMENT       | (FAIR) · Attn                        |                            |     |        |
| BKT Cylinder     | FAIR · (Attn)                        | 油漏れ小 OIL LEAKING           |     |        |

|                                                                      |                  |                                       |  |
|----------------------------------------------------------------------|------------------|---------------------------------------|--|
| UNDERCARRIAGE :                                                      |                  | See Photos. 写真参照                      |  |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         |                  | 2                                     |  |
| COMMENT                                                              |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
| BKT                                                                  | (STD)            | SLOPE / NARROW / SKELETON / OTHER ( ) |  |
| Lever                                                                | LONG · (WRIST)   |                                       |  |
| Multi                                                                | (MULTI) · 2 · NO |                                       |  |
| ARM-CRANE                                                            | YES · (NO)       |                                       |  |
| BLADE                                                                | YES · (NO)       |                                       |  |
| OFFSET                                                               | YES · (NO)       |                                       |  |
| OFFSET Cylinder                                                      | FAIR · Attn      |                                       |  |
| Piping                                                               | YES · (NO)       | Breaker only · Multi                  |  |
| COMMENT                                                              |                  |                                       |  |
| 17.25mスーパーロング 17.25m SUPER LONG                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
|                                                                      |                  |                                       |  |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                  | 3                                     |  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。