

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/9/28	CATEGORY	STANDARD BUCKET for ZW180		
MAKE	HITACHI		MODEL	UNKNOWN	
SERIAL	NO PLATE		STAMP	NOT FOUND	
HR METER	—	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE		TIRE

ENGINE	MODEL	S/N
Oil leakage	FAIR ・ Attn	Oil
Blow-By	FAIR ・ Attn	Exhaust Color
Sound	FAIR ・ Attn	EPA

CONDITION	FAIR	Attn	
未確認 OPERATION: NOT CHECKED			

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	—	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR
COMMENT			
75φ × 113mm			
取付ピン欠 NO PINS			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。