

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/9/28	CATEGORY	STANDARD BUCKET for ZW120			
MAKE	HITACHI		MODEL	UNKNOWN		
SERIAL	NO PLATE		STAMP	NOT FOUND		
HR METER	—	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE		TIRE	

ENGINE	MODEL	S/N
Oil leakage	FAIR ・ Attn	Oil FAIR ・ Attn
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE Exhaust Color FAIR ・ Attn
Sound	FAIR ・ Attn	EPA YES ・ NO

CONDITION	FAIR	Attn	
未確認 OPERATION: NOT CHECKED			

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	—	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR
COMMENT			
BUCKET: 74φ × 95mm, ARM: 74φ × 97mm			
取付ピン欠 NO PINS			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。