INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/9/28	MAKE	HITACHI	MODEL	ZX160LC
SERIAL	HCM1F100C00005854		STAMP	HCM1F100C00005854	
HR METER	8481 HR		YEAR	YR	
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL 4BG1 S/N 197452		
Oil leakage	FAIR ・(Attn)	油漏れ小 OIL LEAKING
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	(YES)・ NO	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	FAIR ・(Attn)	にじみあり OIL OOZING
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	ガタあり SWING: LOOSE
Travel	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	破れ大 TORN
Glasses	(FAIR)・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	(FAIR)・ Attn	
Boom Cylinder	FAIR ・(Attn)	左右油漏れあり CYLINDERS: OIL LEAKING
Arm	(FAIR)・ Attn	へコミ、ガタあり DENT, LOOSE
Arm Cylinder	FAIR ・(Attn)	油漏れあり OIL LEAKING
ATTACHMENT	(FAIR)・ Attn	
BKT Cylinder	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	
COMMENT		
スイベル下油漏れあり BOTTOM OF SWIVEL: OIL LEAKING		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG ・ (WRIST)	
Multi	MULTI ・ 2 ・ (NO)	
ARM-CRANE	YES ・(NO)	
BLADE	YES ・(NO)	
OFFSET	YES ・(NO)	
OFFSET Cylinder	FAIR ・ Attn	
Piping	(YES) ・ NO	Breaker only ・ Multi 5
COMMENT		
底板油汚れあり BOTTOM: OIL STAINS		
リペイントあり REPAINTED		
コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING		
A/C冷えない A/C: MALFUNCTION		
ブーム背面ホースひび割れあり		
SOME HOSE AROUND BOOM: A LITTLE DAMAGED		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。