

DUMP TRUCK ダンプ

INSPECTION DATE		2026/9/24	CATEGORY	ON-ROAD DUMP	OFF-ROAD DUMP
MAKE	VOLVO			MODEL	A35
SERIAL	A35V1782			STAMP	NOT FOUND
HR METER	20329	HR	ODOMETER	6551	km
TIRE SIZE	26.5R25			YEAR	YR

ENGINE : MODEL		TD122GA	S/N	194611	
Oil leakage	FAIR · Attn				
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE			
Sound	FAIR · Attn				
Oil	FAIR · Attn				
Exhaust Color	FAIR · Attn	白煙大 MUCH WHITE FUMES			
US EPA	YES · NO				
OPERATION PUMP					
Sound	FAIR · Attn				
Oil leakage	FAIR · Attn				
Power	FAIR · Attn				
COOLING SYSTEM					
Radiator	FAIR · Attn				
Oil Cooler	FAIR · Attn				
TRANSMISSION & TRAVEL					
T/M TYPE	AT · MT		No. OF GEARS	3 GEARS	
Transmission	FAIR · Attn				
4WD	4WD · 2WD				
Travel	FAIR · Attn				
Articulate	FAIR · Attn				
FOOT BRAKE	FAIR · Attn				
PARKING BRAKE	FAIR · Attn				
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN · FAIR · DIRTY				
Operator's Seat	FAIR · Attn				
Glasses	FAIR · Attn				
AirCon	A/C · H/C · H only · C only · None				

MAIN FRAME			
MAIN FLAME		FAIR	▪ Attn
VESSEL			
MAKE			
VESSEL		FAIR	▪ Attn
REAR GATE TYPE		NORMAL ▪ L-GATE (FLAT)	
REAR GATE		FAIR	▪ Attn
UNDERCARRIAGE: See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
TIRE WEAR		FAIR ▪ WORN ▪ UNEVEN WEAR	
COMMENT			
左Rタイヤ後ろ側中央部ワイヤー見えあり			
STEEL BELT OF REAR ONE OF REAR LEFT TIRES: PARTLY BARED			
右Fタイヤ傷あり FRONT RIGHT TIRE SIDEWALL: HUGE CUT			
E/Gフードロック部破損あり ENGINE HOOD LOCK: BROKEN			
ROPS-CAB			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。