

INSPECTION SHEET 検品書
TRUCKトラック

INSPECTION DATE	2026/10/9	MAKE	ISUZU	MODEL	KK-NQR72GN
SERIAL	7400061			STAMP	NQR72G-7400061
HR METER	UNKNOWN	HR	Odometer	84038	km
TIRE	7.50R16			YEAR	YR

ENGINE : MODEL 4HJ1 S/N			
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	AT	MT	No. OF GEARS 6 GEARS
Transmission	FAIR	Attn	
4WD	4WD	2WD	
Travel	FAIR	Attn	
FOOT BRAKE	FAIR	Attn	
PARKING BRAKE	FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	切れあり CUT
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only ・ C only ・ NONE
OUTRIGGERS / JACK			
OUTRIGGERS	X	H	
CONDITION	FAIR	Attn	
JACK	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
TIRE WEAR FAIR ・ WORN ・ UNEVEN WEAR			
COMMENT			
BODY			
CATEGORY	散水車 ROAD SPRINKLER		
MAKE	KYOKUTO		
MODEL	LH04-30R	SERIAL	01L074007N
CONDITION	FAIR	Attn	散水不良 MALFUNCTION TO SPRINKLE
MAIN FRAME	FAIR	Attn	サビあり RUSTY
CRANE			
MAKE			
MODEL		SERIAL	
No. of Section	SECTIONS		
HOOK			
RADIO CONTROL	YES	NO	
COMMENT			
A/C風が出ない、S/W入らない			
A/C: NOT BLOWING AIR, UNABLE TO TURN ON			
警告灯点灯あり WARNING LAMP: ON			
最大容量 MAXIMUM WATER CAPACITY: 4000L			
最高出力 MAXIMUM OUTPUT: 114kW/3100rpm			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			
			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。