INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/10/6	MAKE	SUMITOMO	MODEL	SH75X-6A
SERIAL	SMT075X6K00SD5477		STAMP	SMT075X6K00SD5477	
HR METER	3669 HR		YEAR	2016 YR	
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL 4LE2 S/N 652502		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	穴あり HOLES
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	(FAIR) · Attn	
Boom Cylinder	(FAIR) · Attn	
Arm	(FAIR) · Attn	ガタあり LOOSE
Arm Cylinder	(FAIR) · Attn	
ATTACHMENT	(FAIR) · Attn	
BKT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG · (WRIST)	
Multi	MULTI · 2 · (NO)	
ARM-CRANE	(YES) · NO	
BLADE	(YES) · NO	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · (NO)	Breaker only · Multi

COMMENT

リペイントあり REPAINTED

7602エラー表示あり(電気系統異常、E/Gオイル圧力)

"7602" ERROR DISPLAY

FOR ELECTRIC SYSTEM & ENGINE OIL PRESSURE

入庫時アイドリング安定しない(3秒くらいで上がったり下がったりを繰り返す)、

しばらくしたらアイドリングが高い状態で安定したがアクセルコントロールが不可になった

IDLING: UNSTABLE WHEN BRINGING THIS MACHINE IN THE NARITA YARD

(ENGINE IDLE SPEED: REPEATEDLY RISING & FALLING

EVERY AROUND 3 SECONDS),

ABLE TO KEEP HIGH ENGINE IDLE SPEED AFTER SOME TIME

BUT NO ACCELERATOR CONTROL

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。