

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/9/24	MAKE	FURUKAWA	MODEL	FL180- I
SERIAL	1072		STAMP	F22-1072	
HR METER	9534	HR	Odometer	63415	km
CAB/CNP	ROPS CAB	/ CAB	ROPS CNP	/ CNP	/ NONE
TIRE SIZE	17.5-25 12PR (SNOW)				

ENGINE : MODEL 6BD1 S/N	
Oil leakage	FAIR · ☒ Attn E/G周りにじみあり AROUND ENGINE: OIL OOZING
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	FAIR · ☒ Attn 黒煙あり BLACK FUMES
US EPA	YES · ☒ NO
OPERATION PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ PS · DD
Transmission	☒ FAIR · Attn
Travel	☒ FAIR · Attn
FOOT BRAKE	☒ FAIR · Attn
PARKING BRAKE	☒ FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	FAIR · ☒ Attn 破れあり CUTS
Glasses	☒ FAIR · Attn
AirCon	A/C · H/C · ☒ H only · C only · None
FRONT & CYLINDERS	
Arm	FAIR · ☒ Attn *1
Bell crank	☒ FAIR · Attn
Bucket	☒ FAIR · Attn
Articulate	☒ FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES · ☒ NO
ATTACHMENTS	
STD BKT	☒ YES · OTHER
BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO
COMMENT	
ワンタッチ付 W/ONE-TOUCH	
ヒーター故障あり HEATER: MALFUNCTION	
下周りにじみあり BOTTOM: OIL OOZING	
*1 左シリンダーにじみあり LEFT CYLINDER: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。