

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/9/24	CATEGORY	MULTI PLOW for WA100			
MAKE	KOMATSU			MODEL	PSB100-5A	
SERIAL	1021			STAMP	NOT FOUND	
HR METER	-	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE		TIRE

ENGINE	MODEL			S/N		
Oil leakage	FAIR	Attn		Oil	FAIR	Attn
Blow-By	FAIR	Attn	A LITTLE	MIDDLE	SEVERE	Exhaust Color
Sound	FAIR	Attn		EPA	YES	NO

CONDITION	FAIR	Attn	
未確認 OPERATION: NOT CHECKED			

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	-	TIRE WEAR	FAIR
COMMENT			
リペイントあり REPAINTED			
取付ホース4本あり W/4 HOSES			
ワンタッチ式 ONE-TOUCH TYPE			
53φ × 938mm			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。