# INSPECTION SHEET 検品書
## WHEEL LOADER タイヤショベル

| | | | | | |
|---|---|---|---|---|---|
| INSPECTION DATE | 2026/9/29 | MAKE | KOMATSU | MODEL | WA380-6 |
| SERIAL | 66410 | | | STAMP | WA095-66410 |
| HR METER | 16311 HR | Odometer | 52125 km | YEAR | YR |
| CAB/CNP | (ROPS CAB) / CAB / ROPS CNP / CNP / NONE | | | TIRE SIZE | 23.5-25 |

| ENGINE : MODEL | | S/N |
|---|---|---|
| Oil leakage | (FAIR) · Attn | |
| Blow-By | (FAIR) · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | (FAIR) · Attn | |
| Oil | (FAIR) · Attn | |
| Exhaust Color | (FAIR) · Attn | |
| US EPA | YES · (NO) | |
| **OPERATION PUMP** | | |
| Sound | (FAIR) · Attn | |
| Oil leakage | (FAIR) · Attn | |
| Power | (FAIR) · Attn | |
| **COOLING SYSTEM** | | |
| Radiator | (FAIR) · Attn | |
| Oil Cooler | (FAIR) · Attn | |
| **TRANSMISSION & TRAVEL** | | |
| T/M TYPE | (PS) · DD | |
| Transmission | (FAIR) · Attn | |
| Travel | (FAIR) · Attn | |
| FOOT BRAKE | (FAIR) · Attn | |
| PARKING BRAKE | (FAIR) · Attn | |
| **INTERIOR** | See Photos. 写真参照 | |
| INTERIOR COND. | CLEAN · (FAIR) · DIRTY | |
| Operator's Seat | (FAIR) · Attn | 摩耗あり WORN |
| Glasses | (FAIR) · Attn | |
| AirCon | (A/C) · H/C · H only · C only · None | |
| **FRONT & CYLINDERS** | | |
| Arm | (FAIR) · Attn | |
| Bell crank | (FAIR) · Attn | |
| Bucket | (FAIR) · Attn | |
| Articulate | (FAIR) · Attn | |

| UNDERCARRIAGE : See Photos. 写真参照 | | | |
|---|---|---|---|
| **RUST**(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | | |
| TIRE WEAR | FAIR (WORN) UNEVEN WEAR | | |
| **COMMENT** | | | |
| STEERING TYPE | (WHEEL STEERING) / COMMAND STEERING / LEVER STEERING | | |
| RIDE CONTROL | (YES) · NO | | |
| **ATTACHMENTS** | | | |
| STD BKT | (YES) · OTHER | | |
| BLADE | YES · (NO) | Piping for Tilt | YES · (NO) |
| **COMMENT** | | | |
| **RUST of BODY**(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。