

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/9/17	MAKE	KOMATSU	MODEL	WA30-6E0		
SERIAL	101158			STAMP	WA131-101158		
HR METER	5821	HR	Odometer	-	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	12.5/70-16 6PR		

ENGINE :		MODEL	3D88E	S/N	37908
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE	MIDDLE	SEVERE
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	(FAIR)	Attn			
US EPA	YES	(NO)			
OPERATION PUMP					
Sound	(FAIR)	Attn			
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
TRANSMISSION & TRAVEL					
T/M TYPE	(PS)	DD			
Transmission	(FAIR)	Attn			
Travel	(FAIR)	Attn			
FOOT BRAKE	(FAIR)	Attn			
PARKING BRAKE	(FAIR)	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	(FAIR)	DIRTY		
Operator's Seat	(FAIR)	Attn			
Glasses	(FAIR)	Attn			
AirCon	A/C	H/C	(H only)	C only	None
FRONT & CYLINDERS					
Arm	(FAIR)	Attn			
Bell crank	(FAIR)	Attn			
Bucket	(FAIR)	Attn			
Articulate	(FAIR)	Attn			
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
TIRE WEAR (FAIR) WORN UNEVEN WEAR					
COMMENT					
STEERING TYPE (WHEEL STEERING / COMMAND STEERING / LEVER STEERING)					
RIDE CONTROL YES (NO)					
ATTACHMENTS					
STD BKT (YES) OTHER					
BLADE YES (NO) Piping for Tilt YES (NO)					
COMMENT					
センターピンガタあり CENTER PIN: LOOSE					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					
					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。