

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/10/6	CATEGORY	除雪機 ROTARY SNOW BLOWER		
MAKE	KUBOTA		MODEL	KSR300ADXT	
SERIAL	38811027		STAMP	NOT FOUND	
HR METER	1167	HR	Odometer	km	YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP NONE		SHOE	300R	TIRE

ENGINE	MODEL V1505	S/N
Oil leakage	FAIR ・ Attn	Oil FAIR ・ Attn
Blow-By	FAIR ・ Attn A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color FAIR ・ Attn
Sound	FAIR ・ Attn	EPA YES ・ NO

CONDITION	FAIR ・ Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR
COMMENT			
クラッチ切っても走行する ABLE TO TRAVEL EVEN DECLUTCHING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。