

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2026/9/28	MAKE	KOMATSU	MODEL	FG20-8		
SERIAL	130539			STAMP	NOT FOUND		
HR METER	4257	HR	Odometer	-	km	YEAR	YR
CAB/CNP	CAB / CNP / NONE			TIRE SIZE	F: 175R13(OUTSIDE), 7.00-12(INSIDE) R: 6.00-9		
MAX LIFTING HEIGHT	3.0	m	VIEW	MONO	FORK LENGTH	1220	mm
FORK SPEC	回転式フォーク、サヤ付 ROTARY FORK, W/EXTENSIONS						

ENGINE : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn	*1	
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	PS · DD		
Transmission	FAIR · Attn		
Travel	FAIR · Attn		
FOOT BRAKE	FAIR · Attn	効きが悪い BRAKE: LOOSE	
PARKING BRAKE	FAIR · Attn	効きが悪い BRAKE: LOOSE	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn	破れ小 CUTS	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
HYDRAULICS			
MAST Cylinder	FAIR · Attn		
TILT Cylinder	FAIR · Attn		
UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
TIRE WEAR		FAIR · WORN · UNEVEN WEAR	
COMMENT			
リペイントあり REPAINTED			
燃料メーター不良 FUEL GAUGE: MALFUNCTION			
*1 E/Gオイルやや少ない ENGINE OIL LEVEL: A LITTLE LOW			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。