

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/10/7	MAKE	HITACHI	MODEL	LX130-7			
SERIAL	RYU4G000K00002339			STAMP	S32-02339			
HR METER	9684	HR	Odometer	-	km	YEAR	2005	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25 (SNOW, SPIKE)			

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUT
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
FRONT & CYLINDERS		
Arm	FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4	
TIRE WEAR		FAIR · WORN · UNEVEN WEAR	
COMMENT			
タコメーター TACHOMETER: 3870km			
ステアリングポンプに入っているパイプ油漏れあり			
POWER STEERING PIPE: OIL LEAKING			
STEERING TYPE		WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL		YES · NO	
ATTACHMENTS			
STD BKT		YES · OTHER 除雪ロータリー ROTARY SNOW PLOW	
BLADE		YES · NO Piping for Tilt YES · NO	
COMMENT			
ROTARY SNOW PLOW MAKE: NICHIGO NRT5AJ-11367J191 (2368HR)			
リペイントあり REPAINTED			
ワンタッチ付 W/ONE-TOUCH			
付属品:スタンダードバケット、マルチプラウ			
STANDARD BUCKET & MULTI PLOW AS SPARE			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。