INSPECTION SHEET 検品書

ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/10/22	MAKE	KATO	MODEL	KRM-13H-Ⅲ
SERIAL No.	PLATE : 7811507		STAMP : KRC013-1507		
HR METER	14012 HR		Odometer	102059 km	
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR・(Attn)	E/Gヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	(FAIR)・Attn	A LITTLE・MIDDLE・SEVERE
Sound	(FAIR)・Attn	
Oil	(FAIR)・Attn	
Exhaust Color	(FAIR)・Attn	
OPERATION PUMP		
Sound	(FAIR)・Attn	
Oil leakage	(FAIR)・Attn	
Power	(FAIR)・Attn	
COOLING SYSTEM		
Radiator	(FAIR)・Attn	
Oil Cooler	(FAIR)・Attn	
OPERATING SYSTEM		
Computer	(OK)・NG	
Swing	(FAIR)・Attn	
Travel	(FAIR)・Attn	
TRANSMISSION		
Transmission	(FAIR)・Attn	
No. OF GEARS	4 GEARS	
4WD	(4WD)・6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・(FAIR)・DIRTY	
Operator's Seat	(FAIR)・Attn	
Glasses	(FAIR)・Attn	
AirCon	(A/C)・H/C・H only・C only・None	
COMMENT		

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	(FAIR)・Attn	
DERRICKING CYL.	(FAIR)・Attn	
EXTENSION CYL.	(FAIR)・Attn	
JIB	(YES)・NO	
JIB TYPE	STD・(PWR)	
MAIN & SUB WIRE	(YES)・NO	
FREE FALL	YES・(NO)	
HOOK	13t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		1
TIRE WEAR	(FAIR)・WORN・UNEVEN WEAR	
COMMENT		

OUTRIGGERS				
OUTRIGGERS	X・(H)			
OUTRIGGERS COND.	(FAIR)・Attn			
Oil leakage (JACK CYL.)	FRONT L・R	REAR L・R		
Oil leakage (SLIDE CYL.)	FRONT L・R	REAR L・R		
COMMENT				
コントロールバルブにじみあり CONTROL VALVE: OIL OOZING				
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。