

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/10/1	MAKE	KOMATSU	MODEL	WA380-5
SERIAL	61016			STAMP	W097-61016
HR METER	22233	HR	Odometer	102457	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.5-25 16PR (SNOW, SPIKE)

ENGINE : MODEL 6D114E-2 S/N	
Oil leakage	FAIR · ☒ Attn E/G周りにじみあり AROUND ENGINE: OIL OOZING
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ Attn
Oil	☒ Attn
Exhaust Color	☒ Attn
US EPA	☒ YES · NO
OPERATION PUMP	
Sound	☒ Attn
Oil leakage	☒ Attn
Power	☒ Attn
COOLING SYSTEM	
Radiator	☒ Attn
Oil Cooler	☒ Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ PS · DD
Transmission	FAIR · ☒ Attn *1
Travel	☒ Attn
FOOT BRAKE	☒ Attn
PARKING BRAKE	☒ Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	FAIR · ☒ Attn 穴あり HOLE
Glasses	☒ Attn
AirCon	☒ A/C · H/C · H only · C only · None
FRONT & CYLINDERS	
Arm	FAIR · ☒ Attn 左右シリンダーにじみあり CYLINDERS: OIL OOZING
Bell crank	☒ Attn
Bucket	FAIR · ☒ Attn シリンダーにじみあり CYLINDER: OIL OOZING
Articulate	☒ Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR	
COMMENT	
下周り油漏れあり BOTTOM: OIL LEAKING	
タコメーター TACHOMETER: 105719km	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	☒ YES · NO
ATTACHMENTS	
STD BKT	☒ YES · OTHER
BLADE	YES · ☒ NO Piping for Tilt ☒ YES · NO
COMMENT	
E01表示あり "E01" ERROR DISPLAY	
*1 周り付近ホース油漏れあり	
*1 SOME HOSE AROUND TRANSMISSION: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。