

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/4/27	MAKE	KOMATSU	MODEL	D20PLL-7E
SERIAL	62631			STAMP	D20PL7E-62631
HR METER	7412	HR	SHOE	1050LGP	YEAR YR
BLADE	STRAIGHT / <u>ST/TILT</u> / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE

ENGINE : MODEL S/N		UNDERCARRIAGE See Photos. 写真参照	
Oil leakage	<u>FAIR</u> · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	
Blow-By	<u>FAIR</u> · Attn	COMMENT	
Sound	<u>FAIR</u> · Attn		
Oil	<u>FAIR</u> · Attn		
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	YES · <u>NO</u>		
OPERATION PUMP		Ripper	MULTI · S/S Shanks PCS
Sound	<u>FAIR</u> · Attn	Ripper CYLD.	FAIR · Attn
Oil leakage	<u>FAIR</u> · Attn	COMMENT	
Power	<u>FAIR</u> · Attn	A/Cベルト欠、A/C故障あり A/C: NO BELT, MALFUNCTION	
COOLING SYSTEM			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	PS · <u>DD</u>	DIFF. STEERING	YES · <u>NO</u>
Transmission	<u>FAIR</u> · Attn		
Travel	<u>FAIR</u> · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · <u>DIRTY</u>		
Operator's Seat	FAIR · <u>Attn</u>	破れあり HUGE CUTS	
Glasses	<u>FAIR</u> · Attn		
AirCon	<u>A/C</u> · H/C · H only · C only · None		
BLADE & CYLINDERS			
BLADE	<u>FAIR</u> · Attn		
CYLD.(R)	<u>FAIR</u> · Attn		
CYLD.(L)	<u>FAIR</u> · Attn		
TILT CYLD	<u>FAIR</u> · Attn		
ANGLE CYLD	FAIR · Attn	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。