

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/10/5	MAKE	KOMATSU	MODEL	D5	
SERIAL	67J779			STAMP	67J779	
HR METER	47	HR	SHOE	460G	YEAR	YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL		S/N		UNDERCARRIAGE See Photos. 写真参照	
Oil leakage	<u>FAIR</u> · Attn			RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE		COMMENT	
Sound	<u>FAIR</u> · Attn				
Oil	<u>FAIR</u> · Attn				
Exhaust Color	<u>FAIR</u> · Attn				
US EPA	YES · <u>NO</u>				
OPERATION PUMP				Ripper	MULTI · S/S Shanks PCS
Sound	<u>FAIR</u> · Attn			Ripper CYLD.	FAIR · Attn
Oil leakage	<u>FAIR</u> · Attn			COMMENT	
Power	<u>FAIR</u> · Attn			CAB周り溶接あり AROUND CAB: WELDED	
COOLING SYSTEM				オイルエレメントにじみあり OIL FILTER: OIL OOZING	
Radiator	<u>FAIR</u> · Attn			左ドア取っ手固着あり、開かない(中からは開く)	
Oil Cooler	<u>FAIR</u> · Attn			LEFT DOOR LEVER: STUCK, UNABLE TO OPEN FROM OUTSIDE	
TRANSMISSION & TRAVEL				E/Gストップ不良 ENGINE STOPPER: MALFUNCTION	
T/M TYPE	PS · <u>DD</u>	DIFF. STEERING	YES · <u>NO</u>	燃料メーター不良 FUEL GAUGE: MALFUNCTION	
Transmission	<u>FAIR</u> · Attn			*1 F、F左下クラックあり	
Travel	<u>FAIR</u> · Attn			*1 UPPER WINDSHIELD & LOWER LEFT WINDSHIELD: CRACKED	
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN · FAIR · <u>DIRTY</u>				
Operator's Seat	FAIR · <u>Attn</u>	破れあり CUT			
Glasses	FAIR · <u>Attn</u>	*1			
AirCon	A/C · H/C · H only · C only · <u>None</u>				
BLADE & CYLINDERS					
BLADE	<u>FAIR</u> · Attn				
CYLD.(R)	<u>FAIR</u> · Attn	サビ付着あり RUSTY			
CYLD.(L)	<u>FAIR</u> · Attn	サビ付着あり RUSTY			
TILT CYLD	FAIR · Attn				
ANGLE CYLD	FAIR · Attn			RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。