

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/10/10	MAKE	KOMATSU	MODEL	PC120-8
SERIAL	84974			STAMP	UNREADABLE
HR METER	10545	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL		S/N
Oil leakage	FAIR · ☒ Attn	*1
Blow-By	FAIR · ☒ Attn	A LITTLE · MIDDLE · ☒ SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
US EPA	YES · ☒ NO	
MAIN PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	FAIR · ☒ Attn	*2
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY	
Operator's Seat	☒ FAIR · Attn	
Glasses	FAIR · ☒ Attn	右一面ガラス欠 RIGHT SIDE GLASS: MISSING
AirCon	☒ A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	☒ FAIR · Attn	
Boom Cylinder	FAIR · ☒ Attn	*3
Arm	☒ FAIR · Attn	
Arm Cylinder	☒ FAIR · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	☒ FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
シューブッシュ摩耗あり PIN BUSHES: WORN	
運転席下底板油漏れあり BOTTOM OF CAB: OIL LEAKING	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG · ☒ WRIST
Multi	MULTI · 2 · ☒ NO
ARM-CRANE	YES · ☒ NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	☒ YES · NO Breaker only · Multi 5
COMMENT	
ラジエータ下底板油漏れあり BOTTOM OF RADIATOR: OIL LEAKING	
コントロールバルブ左横下辺り油漏れあり	
AROUND LOWER LEFT PART OF CONTROL VALVE: OIL LEAKING	
E/G始動難あり(E/G圧縮低下により掛かり悪い)	
HARD TO START THE ENGINE (LOW ENGINE COMPRESSION)	
作業機オーバーヒート歴あり MAIN PUMP: OVERHEATING	
アタッチメントなし WITHOUT ATTACHMENT	
*1 ドレイン油漏れ小、クランクシール油漏れあり	
*1 DRAIN & CRANK SEAL: OIL LEAKING	
*2 ポンプ下ホース油漏れあり SOME HOSE UNDER PUMP: OIL LEAKING	
*3 左右油漏れ大(吸着マットあり)	
*3 CYLINDERS: SEVERE OIL LEAKING (W/ABSORPTION MATS)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。