INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/10/21	MAKE	KOMATSU	MODEL	PC200-6E
SERIAL	96866			STAMP	PC200-96866 (HARD TO READ)
HR METER	UNKNOWN HR			YEAR	YR
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 6D102E-1 S/N 26206680		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	FAIR · (Attn)	にじみあり OIL OOZING
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	ガタあり SWING: LOOSE
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · (DIRTY)	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	(FAIR) · Attn	
Boom Cylinder	FAIR · (Attn)	左右油漏れあり CYLINDERS: OIL LEAKING
Arm	(FAIR) · Attn	へコミ、ガタあり MUCH DENT, LOOSE
Arm Cylinder	FAIR · (Attn)	にじみあり OIL OOZING
ATTACHMENT	(FAIR) · Attn	
BKT Cylinder	FAIR · (Attn)	油漏れあり OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG · (WRIST)	
Multi	MULTI · 2 · (NO)	
ARM-CRANE	YES · (NO)	
BLADE	YES · (NO)	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	(YES) · NO	Breaker only · (Multi) *1
COMMENT		
全体的にホースひび割れ多数あり MANY HOSES: CRACKED		
右サイドカバー変形あり RIGHT SIDE COVER: MUCH DENT		
コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING		
モニター不良、HRメーター不明		
MONITOR: MALFUNCTION, HR METER: UNKNOWN		
*1 ペダル固着気味 PEDAL: A LITTLE STUCK		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。