INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2026/10/14	MAKE	KOMATSU	MODEL	FD60-5
SERIAL	62931			STAMP	M113-62931
HR METER	E15387 HR	Odometer	– km	YEAR	YR
CAB/CNP	CAB / (CNP) / NONE			TIRE SIZE	8.25-15
MAX LIFTING HEIGHT	4.5 m	(VIEW) / MONO		FORK LENGTH	1200 mm
FORK SPEC					

ENGINE : MODEL	S/N	
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	FAIR · (Attn)	白煙あり WHITE FUMES
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
FOOT BRAKE	FAIR · (Attn)	*1
PARKING BRAKE	(FAIR) · Attn	
INTERIOR	See Photos. 写真参照	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
HYDRAULICS		
MAST Cylinder	FAIR · (Attn)	左右にじみあり CYLINDERS: OIL OOZING
TILT Cylinder	FAIR · (Attn)	左右油漏れあり CYLINDERS: OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR (FAIR) · WORN · UNEVEN WEAR	
COMMENT	
ノーパンクタイヤ SOLID TIRES	
左右ステアリングシリンダーにじみあり STEERING CYLINDERS: OIL OOZING	
HRメーターストップ HR METER: STOPPED	
全体的にホースひび割れ多数あり MANY HOSES: MUCH CRACKED	
メーター不良 METERS: MALFUNCTION	
ミッション周りホース油漏れあり(ホース？)	
AROUND TRANSMISSION (HOSE?): OIL LEAKING	
F周りホース油漏れあり SOME HOSE AROUND FRONT PART: OIL LEAKING	
リペイントあり REPAINTED	
*1 効くが踏み続けると抜ける	
*1 BRAKE: NOT WORKING BY CONTINUING STEPPING ON THE PEDAL	
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。