INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2026/10/14	MAKE	KOMATSU	MODEL	FD60-5
SERIAL	62021			STAMP	M113-62021
HR METER	UNKNOWN HR	Odometer	– km	YEAR	YR
CAB/CNP	CAB / (CNP) / NONE			TIRE SIZE	F: 7.50-15 R: 8.25-15
MAX LIFTING HEIGHT	4.0 m	(VIEW) / MONO		FORK LENGTH	1440 mm
FORK SPEC					

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	FAIR · (Attn)	白煙小 A LITTLE WHITE FUMES
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
FOOT BRAKE	FAIR · (Attn)	効き甘い BRAKE: LOOSE
PARKING BRAKE	(FAIR) · Attn	
INTERIOR	**See Photos. 写真参照**	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	破れあり CUT
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
HYDRAULICS		
MAST Cylinder	(FAIR) · Attn	
TILT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR (FAIR) · WORN · UNEVEN WEAR	

COMMENT

ノーパンクタイヤ SOLID TIRES

E/Gフードダンパー不良 ENGINE HOOD DAMPER: MALFUNCTION

マストのチェーン滑車固着気味

MAST CHAIN SHEAVE: A LITTLE STUCK

HRメーター欠 HR METER: MISSING

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。