

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/9/2	MAKE	KOMATSU	MODEL	WA300-3E		
SERIAL	53209			STAMP	W039-53209		
HR METER	12937	HR	Odometer	-	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25 12PR		

ENGINE :		MODEL	6D108E-2	S/N	30113
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	(FAIR)	Attn			
US EPA	YES	(NO)			
OPERATION PUMP					
Sound	(FAIR)	Attn			
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
TRANSMISSION & TRAVEL					
T/M TYPE	(PS)	DD			
Transmission	(FAIR)	Attn			
Travel	(FAIR)	Attn			
FOOT BRAKE	(FAIR)	Attn			
PARKING BRAKE	(FAIR)	Attn			
INTERIOR		See Photos. 写真参照			
INTERIOR COND.	CLEAN	·	(FAIR)	·	DIRTY
Operator's Seat	(FAIR)	Attn			
Glasses	(FAIR)	Attn			
AirCon	(A/C)	·	H/C	·	H only · C only · None
FRONT & CYLINDERS					
Arm	FAIR	(Attn)	*1		
Bell crank	(FAIR)	Attn			
Bucket	(FAIR)	Attn			
Articulate	(FAIR)	Attn			
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
TIRE WEAR		FAIR · (WORN) · UNEVEN WEAR			
COMMENT					
タコメーター TACHOMETER: 87696km					
STEERING TYPE (WHEEL STEERING / COMMAND STEERING / LEVER STEERING)					
RIDE CONTROL		YES · (NO)			
ATTACHMENTS					
STD BKT		(YES) · OTHER			
BLADE		YES · (NO) Piping for Tilt (YES) · NO *2			
COMMENT					
ワンタッチ付 W/ONE-TOUCH					
ラジオ音出ない RADIO: NOT SPEAKING					
下周り油漏れあり BOTTOM: OIL LEAKING					
付属品: マルチプラウ(左シリンダーにじみ、溶接あり)					
MULTI PLOW AS SPARE (LEFT CYLINDER: OIL OOZING, WELDED)					
*1 右シリンダーにじみあり RIGHT CYLINDER: OIL OOZING					
*2 配管ホース4本欠 4 HOSES: MISSING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。