

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/10/8	MAKE	HITACHI	MODEL	LX50-2C		
SERIAL	40H-1191			STAMP	F19A-1191		
HR METER	4115	HR	Odometer	–	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5/65-20		

ENGINE : MODEL		4TNE98	S/N	00283
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY				
Operator's Seat	FAIR • Attn	破れあり CUTS			
Glasses	FAIR • Attn				
AirCon	A/C • H/C • H only • C only • None				

FRONT & CYLINDERS

Arm	FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

TIRE WEAR	FAIR • WORN • UNEVEN WEAR
-----------	---------------------------

COMMENT

タイヤ全て劣化あり ALL TIRES: DETERIORATED

STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING

RIDE CONTROL	YES	☒ NO
--------------	-----	-------------------------------------

ATTACHMENTS

STD BKT	☒ YES • ☐ OTHER
---------	--

BLADE	YES	☒ NO	Piping for Tilt	YES	☒ NO
-------	-----	-------------------------------------	-----------------	-----	-------------------------------------

COMMENT

作動油点検口キャップ欠 HYDRAULIC OIL FILLER CAP: MISSING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。