INSPECTION SHEET 検品書

ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/10/15	MAKE	TADANO	MODEL	TR-350M-3
SERIAL No.	PLATE : 506089		STAMP : TR352-0088		
HR METER	17924 HR		Odometer	131744 km	
TIRE SIZE	445/95R25		YEAR	YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR・(Attn)	*1
Blow-By	FAIR・(Attn)	(A LITTLE)・MIDDLE・SEVERE
Sound	(FAIR)・Attn	
Oil	(FAIR)・Attn	
Exhaust Color	FAIR・(Attn)	黒煙あり BLACK FUMES
OPERATION PUMP		
Sound	(FAIR)・Attn	
Oil leakage	(FAIR)・Attn	
Power	(FAIR)・Attn	
COOLING SYSTEM		
Radiator	(FAIR)・Attn	
Oil Cooler	(FAIR)・Attn	
OPERATING SYSTEM		
Computer	(OK)・NG	
Swing	(FAIR)・Attn	
Travel	(FAIR)・Attn	
TRANSMISSION		
Transmission	(FAIR)・Attn	
No. OF GEARS	4 GEARS	
4WD	(4WD)・6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・(FAIR)・DIRTY	
Operator's Seat	(FAIR)・Attn	
Glasses	(FAIR)・Attn	
AirCon	(A/C)・H/C・H only・C only・None	
COMMENT		

BOOM		
No. of Section	5 SECTIONS	
CRACK/ENFORCEMENT	(FAIR)・Attn	
DERRICKING CYL.	(FAIR)・Attn	
EXTENSION CYL.	(FAIR)・Attn	
JIB	(YES)・NO	
JIB TYPE	STD・(PWR)	
MAIN & SUB WIRE	(YES)・NO	
FREE FALL	(YES)・NO	
HOOK	35t, 20t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1
TIRE WEAR	(FAIR)・WORN・UNEVEN WEAR	
COMMENT		
OUTRIGGERS		
OUTRIGGERS	(X)・H	
OUTRIGGERS COND.	(FAIR)・Attn	
Oil leakage (JACK CYL.)	FRONT L・R	REAR L・R
Oil leakage (SLIDE CYL.)	FRONT L・R	REAR L・R
COMMENT		
穴あり HOLES		
エアー漏れあり AIR LEAKING		
パーキングランプ点かない PARKING LAMP: UNABLE TO LIGHT ON		
パーキングブレーキ効きが悪い PARKING BRAKE: LOOSE		
*1 噴射ポンプ燃料にじみあり INJECTION PUMP: FUEL OOZING		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。