INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/10/7	MAKE	CAT	MODEL	311FLRR
SERIAL	CAT0311FVJFT10474		STAMP	CAT0311FVJFT10474	
HR METER	10964 / 10956 HR		YEAR	YR	
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL C3.4B S/N CNW09059		
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	(YES)・ NO	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・ FAIR・ (DIRTY)	
Operator's Seat	(FAIR)・ Attn	
Glasses	(FAIR)・ Attn	
AirCon	(A/C)・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	(FAIR)・ Attn	
Boom Cylinder	FAIR ・(Attn)	左右にじみあり CYLINDERS: OIL OOZING
Arm	(FAIR)・ Attn	ガタあり LOOSE
Arm Cylinder	FAIR ・(Attn)	メッキ剥がれ大 COATING: MUCH PEELED
ATTACHMENT	(FAIR)・ Attn	ガタあり LOOSE
BKT Cylinder	FAIR ・(Attn)	傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG ・ (WRIST)	
Multi	(MULTI)・ 2 ・ NO	
ARM-CRANE	YES ・(NO)	
BLADE	YES ・(NO)	
OFFSET	YES ・(NO)	
OFFSET Cylinder	FAIR ・ Attn	
Piping	(YES)・ NO	Breaker only ・ (Multi) *2

COMMENT

*1 ヘッド周りにじみあり AROUND CYLINDER HEAD: OIL OOZING

*2 左右アーム部欠 PIPES & HOSES: PARTLY MISSING

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。