

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/10/1	MAKE	KOMATSU	MODEL	WA100-6		
SERIAL	80226			STAMP	WA115-80226		
HR METER	3056	HR	Odometer	1311	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24 10PR (SNOW, SPIKE)		

ENGINE : MODEL		4D95LE-5	S/N	514845
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN FAIR DIRTY				
Operator's Seat	FAIR	Attn			
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None

FRONT & CYLINDERS

Arm	FAIR	Attn	
Bell crank	FAIR	Attn	
Bucket	FAIR	Attn	サイドシャッター付 W/SIDE SHUTTERS
Articulate	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

TIRE WEAR (FAIR • WORN • UNEVEN WEAR)

COMMENT

タコメーター TACHOMETER: 19458km

STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING

RIDE CONTROL	☒ YES	☐ NO
--------------	--------------------------------------	--------------------------

ATTACHMENTS

STD BKT	☒ YES • ☐ OTHER	
---------	--	--

BLADE	☒ YES ▪ NO	Piping for Tilt	☒ YES ▪ NO
-------	---	-----------------	---

COMMENT

左ドア開きにくい LEFT DOOR: HARD TO OPEN

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。