

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE		2026/10/9		MAKE		TADANO		MODEL		AT-121-3	
SERIAL No.		PLATE : HJ2828				STAMP :		NOT FOUND			
HR METER		3768		HR		Odometer		61789		km	
YEAR				YR							
CHASSIS		MODEL TKG-NKR85N				No.		NKR85-7036564			
SHOE						TIRE SIZE		205/85R16			
MAX HIGHT		12.0				m		MAX WEIGHT		200	
								kg			

ENGINE : MODEL 4JJ1 S/N			
Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE *1
Sound	FAIR	Attn	*1
Oil	FAIR	Attn	*1
Exhaust Color	FAIR	Attn	*1
US EPA	YES · NO		*1
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	*1
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	*1
Oil Cooler	FAIR	Attn	*1
TRANSMISSION & TRAVEL			
T/M TYPE	AT · MT	No. OF GEARS	- GEARS
Transmission	FAIR	Attn	
4WD	4WD	2WD	
Travel	FAIR	Attn	
Swing	FAIR	Attn	*1
FOOT BRAKE	FAIR	Attn	
PARKING BRAKE	FAIR	Attn	
BOOM			
No. of Section	3	SECTIONS	
DERRICKING CYL.	FAIR	Attn	
EXTENSION CYL.	FAIR	Attn	

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS X · H	
OUTRIGGERS COND.	FAIR · Attn
COMMENT	
キー抜けない IGNITION KEY: UNABLE TO REMOVING	
ジャッキ水平が出ないため上物未点検	
UPPER PART OPERATIONS: NOT CHECKED	
("J-UP" ERROR DISPLAY FOR JACK-UP)	
スペアタイヤあり W/SPARE TIRE	
*1 上物不良のため確認できない(CABヘッド起こせない)	
*1 NOT CHECKED	
(UPPER PART: MALFUNCTION, CAB OVER: UNABLE TO OPEN)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。