

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE		2026/10/9		MAKE		TADANO		MODEL		AT-121-2	
SERIAL No.		PLATE : HJ1498				STAMP :		NOT FOUND			
HR METER		4208		HR		Odometer		61490		km	
YEAR				YR							
CHASSIS		MODEL BDG-NKR85N				No.		NKR85-7008631			
SHOE						TIRE SIZE		205/85R16			
MAX HIGHT		12.0				m		MAX WEIGHT		200	
								kg			

ENGINE : MODEL 4JJ1 S/N			
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	YES	☒ NO	
OPERATION PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	AT	☒ MT	No. OF GEARS 6 GEARS
Transmission	☒ FAIR	Attn	
4WD	4WD	☒ 2WD	
Travel	☒ FAIR	Attn	
Swing	FAIR	☒ Attn 未確認 NOT CHECKED	
FOOT BRAKE	☒ FAIR	Attn	
PARKING BRAKE	☒ FAIR	Attn	
BOOM			
No. of Section	3	SECTIONS	
DERRICKING CYL.	FAIR	☒ Attn 未確認 NOT CHECKED	
EXTENSION CYL.	FAIR	☒ Attn 未確認 NOT CHECKED	

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS X · ☒ H	
OUTRIGGERS COND.	FAIR · ☒ Attn 未確認 NOT CHECKED
COMMENT	
PTO入らないため上部操作、アウトリガー操作未確認	
UPPER PART OPERATIONS & OUTRIGGER OPERATIONS:	
NOT CHECKED (PTO: UNABLE TO TURN ON)	
最高出力 MAXIMUM OUTPUT: 110kW/2800rpm	
スペアタイヤあり W/SPARE TIRE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。