

INSPECTION SHEET 検品書  
LIFTING PLATFORM 高所作業車

|                 |                   |      |          |                    |           |      |    |
|-----------------|-------------------|------|----------|--------------------|-----------|------|----|
| INSPECTION DATE | 2026/10/9         | MAKE | AICHI    | MODEL              | SS12A     |      |    |
| SERIAL No.      | PLATE : 679135    |      |          | STAMP : NOT FOUND  |           |      |    |
| HR METER        | 8251              | HR   | Odometer | 57036              | km        | YEAR | YR |
| CHASSIS         | MODEL KR-NKR81E3N |      |          | No. NKR81E-7013237 |           |      |    |
| SHOE            |                   |      |          | TIRE SIZE          | 205/85R16 |      |    |
| MAX HIGHT       | 11.9 m            |      |          | MAX WEIGHT         | 200 kg    |      |    |

|                         |      |          |                            |
|-------------------------|------|----------|----------------------------|
| ENGINE : MODEL 4HL1 S/N |      |          |                            |
| Oil leakage             | FAIR | Attn     |                            |
| Blow-By                 | FAIR | Attn     | A LITTLE ▪ MIDDLE ▪ SEVERE |
| Sound                   | FAIR | Attn     |                            |
| Oil                     | FAIR | Attn     |                            |
| Exhaust Color           | FAIR | Attn     |                            |
| US EPA                  | YES  | NO       |                            |
| OPERATION PUMP          |      |          |                            |
| Sound                   | FAIR | Attn     |                            |
| Oil leakage             | FAIR | Attn     |                            |
| Power                   | FAIR | Attn     |                            |
| COOLING SYSTEM          |      |          |                            |
| Radiator                | FAIR | Attn     |                            |
| Oil Cooler              | FAIR | Attn     |                            |
| TRANSMISSION & TRAVEL   |      |          |                            |
| T/M TYPE                | AT   | MT       | No. OF GEARS 5 GEARS       |
| Transmission            | FAIR | Attn     |                            |
| 4WD                     | 4WD  | 2WD      |                            |
| Travel                  | FAIR | Attn     |                            |
| Swing                   | FAIR | Attn     |                            |
| FOOT BRAKE              | FAIR | Attn     |                            |
| PARKING BRAKE           | FAIR | Attn     |                            |
| BOOM                    |      |          |                            |
| No. of Section          | 3    | SECTIONS |                            |
| DERRICKING CYL.         | FAIR | Attn     | ロッドサビあり ROD: RUSTY         |
| EXTENSION CYL.          | FAIR | Attn     |                            |

|                                                                      |       |                         |                    |
|----------------------------------------------------------------------|-------|-------------------------|--------------------|
| <b>INTERIOR</b>                                                      |       | <b>See Photos. 写真参照</b> |                    |
| INTERIOR COND.                                                       | CLEAN | FAIR                    | DIRTY              |
| Operator's Seat                                                      | FAIR  | Attn                    | 破れ大 HUGE CUTS      |
| Glasses                                                              | FAIR  | Attn                    |                    |
| AirCon                                                               | A/C   | H/C                     | H only C only None |
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |       |                         |                    |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         |       |                         | 2                  |
| TIRE WEAR                                                            | FAIR  | WORN                    | UNEVEN WEAR        |
| <b>COMMENT</b>                                                       |       |                         |                    |
| クラッチマスター油漏れあり CLUTCH MASTER CYLINDER: OIL LEAKING                    |       |                         |                    |
| OUTRIGGERS                                                           | X     | H                       |                    |
| OUTRIGGERS COND.                                                     | FAIR  | Attn                    |                    |
| <b>COMMENT</b>                                                       |       |                         |                    |
| バケット起伏上げ操作時:同時に右へゆっくり回転してしまう(上下部操作とも)                                |       |                         |                    |
| A LITTLE SWINGING TO RIGHT DURING GOING UP THE BUCKET                |       |                         |                    |
| スペアタイヤ欠 SPARE TIRE: MISSING                                          |       |                         |                    |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |       |                         | 4                  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。