INSPECTION SHEET 検品書

ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/10/15	MAKE	KATO	MODEL	KR-75H
SERIAL No.	PLATE : 6910130		STAMP : KRC012-0130		
HR METER	8324 HR		Odometer	17790 km	
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
OPERATING SYSTEM		
Computer	OK・NG	
Swing	FAIR・Attn	
Travel	FAIR・Attn	
TRANSMISSION		
Transmission	FAIR・Attn	
No. OF GEARS	4 GEARS	
4WD	4WD・6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・FAIR・DIRTY	
Operator's Seat	FAIR・Attn	
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	
COMMENT		

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	FAIR・Attn	
DERRICKING CYL.	FAIR・Attn	
EXTENSION CYL.	FAIR・Attn	
JIB	YES・NO	
JIB TYPE	STD・PWR	
MAIN & SUB WIRE	YES・NO	
FREE FALL	YES・NO	
HOOK	48t/75t, 35t, BALL, SHEAVE×2	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
TIRE WEAR	FAIR・WORN・UNEVEN WEAR	
COMMENT		
右1・4軸目タイヤサイドひび割れあり		
FRONTEST RIGHT & REAREST RIGHT TIRE SIDEWALLS: CRACKED		
OUTRIGGERS		
OUTRIGGERS	X・H	
OUTRIGGERS COND.	FAIR・Attn *1	
Oil leakage (JACK CYL.)	FRONT L・R	REAR L・R
Oil leakage (SLIDE CYL.)	FRONT L・R	REAR L・R
COMMENT		
左1・2・3軸目タイヤサイドひび割れあり		
FRONT LEFT TIRE SIDEWALLS & FRONT ONE OF REAR LEFT TIRE SIDEWALLS: CRACKED		
右1軸目ステアリングシリンダー油漏れあり		
FRONTEST RIGHT STEERING CYLINDER: OIL LEAKING		
48t/75tフック、シーブ×2、ウエイト別置き		
48t/75t HOOK, SHEAVE×2, & WEIGHT: NOT ATTACHED		
*1 縦シリンダー4本メッキ剥がれあり ALL JACK CYLINDERS: COATING PEELED		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。